

INSTRUCTIONS

MEASURE MASTER™ 3KG

DIGITAL SCALE Product #740637

PLEASE READ THESE INSTRUCTIONS CAREFULLY BEFORE USE.

Failure to follow these instructions and warnings will void your warranty.

Thank you for purchasing the Measure Master 3KG Digital Scale. This scale is a precision instrument and with normal care and proper treatment it will provide years of reliable service. Measure Master scales can be used for a variety of purposes, including the precise measuring of fertilizers and dry nutrients.

WARNING!

- Never load the scale with more than 6.61 lbs. (3 Kg) or permanent damage may occur!
- Operate only at normal room temperatures and avoid exposure to extreme heat or cold.
- If scale has been stored in a hot or cold location, allow it to acclimate to normal room temperature for at least one hour before use.
- Keep scale in a clean environment away from dust, dirt, moisture, vibration, air currents and close proximity to other electronic equipment.
- Use only on flat, stable surfaces. Gently place all items to be weighed on tray top only. Avoid shaking, dropping or otherwise shocking the scale.
- When powering up, **wait 10-15 seconds** before weighing to allow internal components to stabilize.
- Do not submerge the scale in water or place in dishwasher. Clean with a soft, dry cloth only.
- Keep scale out of the reach of children or pets.
- Measures accuracy to 0.1g.

FUNCTIONS & OPERATION

AUTO-OFF To conserve battery power, the unit will automatically turn off after 20 seconds of inactivity. To extend battery life further, you can turn off the scale before 20 seconds have elapsed by pressing "ON/OFF/TARE".



OVERLOAD INDICATOR When "O_Ld" is displayed it indicates an overload. Remove excessive load immediately. *Remember, you can permanently damage the scale and void your warranty by overloading it!*

LOW BATTERY INDICATOR: When "Lo" is displayed, batteries must be replaced. Almost all scale function problems are caused by low batteries. They must be replaced for the scale to function properly.

NEGATIVE VALUE Any tared value will be displayed as a negative number once all weight is removed, press "TARE" or cycle the power to re-zero the scale.



Measure Master 3KG Controls and LCD Display



ON/OFF/TARE (3 Functions):

1. If scale is off, press to turn on. Unit self-tests and displays all characters, then resets to "0.00." NOTE: If scale is not stable or level "Unst" will be displayed.
2. If scale is on and displaying "0.00," place empty container on platform and wait for the container's weight to be displayed. Press once to activate TARE function, which will reset the scale to "0.00." You can now weigh any contents you add to the container *minus* the weight of the container itself.
3. If scale is on, press and hold for 2 seconds to turn power off. Unit will also power off automatically after 20 seconds of inactivity.

MODE: With the scale on (loaded or not), press to cycle through "oz" (ounces), "ml" (milliliter) or "m" "ml" (milliliter of milk). NOTE: To access "g" grams or "lb" pounds use "UNIT" key on bottom of scale (see "UNIT" immediately below).

UNIT: With the scale on (loaded or not), press "MODE" key until "oz 0.00" is displayed, then press the "UNIT" key to cycle between "g" grams, "lb" pounds or "oz" ounces.

SPECIFICATIONS

Measuring Range	.0035 oz. to 6.61 lbs.
Scale Dimensions	7" x 8.25" x 1.375"
Tray Dimensions	6.875" Diameter
Scale Weight	12.93 oz.
Operating Range	50-104°F (10-40°C)
Power	3VDC (2 AAA)
Tare Range	up to 3 Kg

Other Measure Master Products

SCALES:

- 7000 Large Capacity Platform Scale
- 5000XL Extra Large Capacity Digital Scale
- 5000 Large Capacity Digital Scale
- 3000 Precision Digital Scale
- 1000 Precision Digital Scale
- 500 Pocket Scale
- 400 High Accuracy Digital Scale
- 15KG Platform Scale
- 5KG Small Platform Scale

MEASURING CONTAINERS:

- Measuring Shot Glasses
- Graduated Containers (Rectangular, Round and Beaker)
- 5 Gallon Measuring Bucket
- Sterile Disposable Pipettes
- Measuring Spoons
- Graduated Dropper
- Graduated Garden Syringe
- 1 Oz. Pump Dispensers

Exclusively distributed by:



Sunlight Supply, Inc.

Vancouver, WA 98660 • Sunlight Supply.com

WWW.MEASUREMASTER.NET